



# Dichtungsvollsatz, Motor

## Mercedes-Benz

### OM 447 HA | HLA

<p><b>OM 447 H</b>  <b>OM 447 HA</b>  <b>OM 447 HLA</b>  <b>OM 447 HO</b>            447.905-908/910-913/914/            915/916/950/951/            952-956/957/958/ 959/968/            970-972/980/981/982/983/            984-987/988/990-993/994            6 Cyl.            Cyl. 128,0 Ø</p>	<p>S⊕* 914.983            incl. 896.510            incl. 524.973 (FPM)            incl. 562.920 (FPM)</p> <p>S⊕* 373.190            incl. 896.510            incl. 766.828 (PTFE)            incl. 766.852 (PTFE)</p>	<p></p> <p></p> <p>896.510            442 016 03 20            Metall-Elastomer            1,25 mm            143,5 Ø</p>
<p><b>OM 447 HA/HLA</b>            447.947-949/960/            973-979/995/996/998/999            6 Cyl.            Cyl. 128,0 Ø</p>	<p>S⊕* 374.310            incl. 896.510            incl. 524.973 (FPM)            incl. 562.920 (FPM)</p> <p>S⊕* 373.190            incl. 896.510            incl. 766.828 (PTFE)            incl. 766.852 (PTFE)</p>	<p></p> <p>412.180            442 016 04 20            Metall-Elastomer            1,25 mm            143,5 Ø</p>