



SI 0092
For technical personnel only!
1/1

SERVICE INFORMATION

ADAPTATION TO ENGINE MANAGEMENT

VARIOUS PIERBURG COMPONENTS MUST BE “LEARNT”

Modern vehicles are partly equipped with highly complex electronic components for which in the engine management controller highly specific characteristics data must be saved. When replacing such a component against a new one, the engine management controller must first be made to “learn” the corresponding characteristics. If this is not done, then the result are typical customer complaints like “new component doesn’t work” or, for example, “higher idle speed after installation”.

Affected by this are among other things:

- air mass sensors,
- stepper motors,
- throttle bodies,
- idle speed devices and
- electric EGR valves.

When installing a new component, as a rule, observe the following:

- will according to the manufacturer’s information be an adaptation required?
- does the engine tester provide in its programme for the specific component (“default setting” or “adaptation”)?
- is there a special Pierburg Service Information document which covers the specific component?



Comprehensive Service Informations can be found at:
www.ms-motorservice.com



- 01** Step motor: idling actuator
- 02** Air mass sensor
- 03** Electric drive module (swirl flap actuator)
- 04** Electric EGR valve
- 05** Throttle body “drive-by wire”

All content including pictures and diagrams is subject to change. For assignment and replacement, refer to the current catalogues or systems based on TecAlliance.