


# Tipps vom Dichtungsprofi

Vertriebs-Service Information | VSI Nr.: 10/2007 – Seite 1 von 2

												
<b>Elring Nr. 373.880</b>												
PICK UP (D21)	2.4	i	12V		04.1992	02.1998	91	124	2389	KA24E		
PICK UP (D21)	2.4	i	12V	4WD	04.1992	02.1998	93	124	2389	KA24E		
PICK UP (D22)	2.4	i			02.1998	11.2001	88	120	2389	KA24E		
PICK UP (D22)	2.4	i	4WD		02.1998	11.2001	88	120	2389	KA24E		
TERRANO II (R20)	2.4	4WD			05.1996	01.2002	85	116	2389	KA24E		
TERRANO II (R20)	2.4	4WD			05.1996		87	118	2389	KA24E		
TERRANO II (R20)	2.4	i	12V	4WD	02.1993	06.1996	91	124	2389	KA24E		
<b>Elring Nr. 373.950</b>												
PICK UP (D22)	2.4	i	4WD		12.2001		88	120	2389	KA24E		
<b>Elring Nr. 389.330</b>												
100 NX (B13)	1.6				03.1990	10.1994	66	90	1597	GA16DS		
100 NX (B13)	1.6	SR			09.1993	10.1994	75	102	1597	GA16DE		
ALMERA I Hatchback (N15)	1.4	S,GX,LX			09.1995	03.2000	55	75	1392	GA14DE		
ALMERA I Hatchback (N15)	1.4				09.1995	03.2000	64	87	1392	GA14DE		
ALMERA I Hatchback (N15)	1.6	SR,SLX			09.1995	03.2000	66	90	1597	GA16DE		
ALMERA I Hatchback (N15)	1.6				09.1995	03.2000	73	99	1597	GA16DE		
ALMERA I (N15)	1.4	GX,LX			09.1995	07.2000	55	75	1392	GA14DE		
ALMERA I (N15)	1.4				09.1995	07.2000	64	87	1392	GA14DE		
ALMERA I (N15)	1.6	SLX			09.1995	07.2000	66	90	1597	GA16DE		
ALMERA I (N15)	1.6				09.1995	07.2000	73	99	1597	GA16DE		
PRIMERA Hatchback (P10)	1.6				06.1990	01.1996	66	90	1597	GA16DE/GA16DS		
PRIMERA Hatchback (P10)	1.6				06.1990	06.1993	71	97	1597			
PRIMERA Hatchback (P10)	1.6				06.1993	01.1996	75	102	1597			
PRIMERA (P10)	1.6				06.1990	01.1996	66	90	1597	GA16DE/GA16DS		
PRIMERA (P10)	1.6				06.1990	01.1996	71	97	1597			
PRIMERA Traveller (W10)	1.6	i			07.1990	03.1998	66	90	1597	GA16DE/GA16DS		
PRIMERA Traveller (W10)	1.6	i			03.1994	03.1998	75	102	1597	GA16DE		

Zylinderkopfhaubensatz



**Nissan**



Das Original

# Tipps vom Dichtungsprofi

Vertriebs-Service Information | VSI Nr.: 10/2007 – Seite 2 von 2

							kW/PS		ccm	
<b>Elring Nr. 389.330</b>										
SUNNY III Liftback (N14)	1.4	i			10.1990	05.1995	55	75	1392	GA14DE /GA14DS
SUNNY III Liftback (N14)	1.4	i	16V		10.1990	06.1995	64	87	1392	GA14DE
SUNNY III Liftback (N14)	1.6	i			10.1990	05.1995	66	90	1597	GA16DE/GA16DS
SUNNY III Liftback (N14)	1.6	i	16V		10.1992	05.1995	75	102	1597	GA16DE
SUNNY III Hatchback (N14)	1.4	i			10.1990	05.1995	55	75	1392	GA14DE /GA14DS
SUNNY III Hatchback (N14)	1.4	i	16V		10.1990	05.1995	64	87	1392	GA14DE
SUNNY III Hatchback (N14)	1.6	i			10.1990	05.1995	66	90	1597	GA16DE/GA16DS
SUNNY III Hatchback (N14)	1.6	i	16V		10.1992	05.1995	75	102	1597	GA16DE
SUNNY III Hatchback (N14)	1.6	i	16V	4x4	10.1992	05.1995	75	102	1597	GA16DE
SUNNY III (N14)	1.4	i			10.1990	05.1995	55	75	1392	GA14DE /GA14DS
SUNNY III (N14)	1.4	i	16V		10.1990	06.1995	64	87	1392	GA14DE
SUNNY III (N14)	1.6	i			10.1990	05.1995	66	90	1597	GA16DE/GA16DS
SUNNY III (N14)	1.6	i	16V	4WD	10.1990	05.1995	66	90	1597	GA16DS
SUNNY III (N14)	1.6	i	16V		10.1992	05.1995	75	102	1597	GA16DE
SUNNY III Traveller (Y10)	1.6	i			06.1991		66	90	1597	GA16DE/GA16DS
SUNNY III Traveller (Y10)	1.6	16V	4x4		11.1990	05.1995	66	90	1597	GA16DS
SUNNY III Traveller (Y10)	1.6	i	16V	4x4	10.1992		75	102	1597	GA16DE
SUNNY Kasten (Y10)	1.6	i	16V		10.1992		66	90	1597	GA16DE



Das Original

ElringKlinger AG | Geschäftsbereich Ersatzteile  
 Max-Eyth-Straße 2 | D-72581 Dettingen/Erms  
 Fon ++49 (0)71 23/724-622 | Fax ++49 (0)71 23/724-609  
 elring@elring.de | www.elring.de